



# OXYGEN PURITY METER(OPM 250)

<b>Sensor</b>	O2 ( EC ) 0.1% Resolution
<b>Ranges</b>	0 - 100%
<b>Response Time</b>	T90 <15 sec with flow > 0 LPM
<b>Display</b>	In-built Graphics Display
<b>Pressure</b>	< 15 PSI
<b>Auto Calibration</b>	User Command for Zero Air Calibration
<b>Battery</b>	Rechargeable (lasts for 20 hours )

